Costing Clear Clarylin : 3855 Lakewood Boulevard Long Boach -- "
Circuit Board FEB 02 1982 DPM 5044

C1-726-124

Hysol Division The Dextor Corporation P. O. Box 312 Pittsburg, California 94565

Attention: Traffic Department

Gentlemen:

This facility must, on occasion, reship your following products:

(PLEASE SEE ATTACHED LIST)

In order to insure our compliance with the Hazardous Materials Redulations of the Department of Transportation, Title 49, Code of .... Federal Regulations, it is requested this office be advised as to whether or not your products are regulated or restricted articles for shipment by surface or air modes of transport.

Should the products be regulated, please indicate:

- DOT Proper Shipping Name per Section 172.101, 49 CFR.
- DOT Hazard Classification per Section 172.101, 49 CFR.
- Flash Point and Closed Cup method per Section 173.115, 49 CFR.
- IATA Article Number.

It is further requested this office be furnished a current copy of the Occupational Safety and Health Administration (OSHA) Material Safety Data Sheet, if available, for all components listed.

Your cooperation and prompt reply will be appreciated.

Very truly yours,

0. Veneroso, Dept. C1-726 (52-11) Materials Handling & Packaging Engineering

Douglas Aircraft Company

MCDONNELL DOUGL

Filler, Hysol 10-001 - -Eiller, Hysol' 10-001; Parts A-&-B-Coating, Hysol 12-059-2 Clear — DMS 1794 eAdhesiver-EA-951-Adhesive - EA-957S DPM 3243 Adhesive; EA-Viii-Resin #4307 "Handonen, 73304 DPM5044 Coating, XPC-H243 Adhosivo-EA-984;-Parts-A-&-B Adhesive; EA-956; Parts A-8-8 Adhesive; EA-8 Catalyst, Guring Agent "A" Adhosive - EA-931-L-Parts A-& B Adhesive, EA 9308, Parts A-&-Bno reply for Items not crossed off

6,3-77